

Name of School or Building	Approximate square footage	Approximate age, years	Roof	Exterior Walls	Exterior Windows	Exterior Accessibility	Exterior Doors
Airport High School Main	285,806	59	Fair	Fair	Poor	Good	Poor
Airport High School- Gym Complex	285,806	13	Fair	Good	Good	Good	Good
Airport High School Vocational	285,806	35	Fair	Good	N/A	Good	Fair
Brookland-Cayce Grammer ES	46,695	63	Fair	Fair	Fair	Fair	Poor
Brooklyn-Cayce- Grammer Relocatables 1-4	2,880	12	Good	Poor	Fair	Good	Fair
Brooklyn-Cayce High School- Main Building	290,105	86	Good	Fair	Fair	Fair	Fair
Brookland-Cayce High School - Vocational Bldg	290,105	86	Poor	Fair	Good	Good	Fair
Brookland-Cayce High School Gym	290,105	86	Fair	Fair	Good	Good	Fair
Claude Taylor ES	39,391	53	Poor	Fair	Poor	Fair	Poor

Name of School or Building	Approximate square footage	Approximate age, years	Roof	Exterior Walls	Exterior Windows	Exterior Accessibility	Exterior Doors
Claude Taylpr ES- Mobile	720	16	Poor	Poor	Not Operational	Not Operational	Poor
Congaree Elementary School	53,544	58	Poor	Fair	Poor	Fair	Poor
Congaree/ Wood Early Childhood	69,513	16	Poor	Poor	Fair	Good	Fair
Cyril B. Busbee Creative Arts Academy	94,852	12	Fair	Fair	Fair	Good	Fair
Davis Early Childhood Center Main	59,561	63	Poor	Good	Good	Good	Good
Davis Early Childhood Center Mobiles 1,2,3, and 4	3,312	12	Poor	Fair	Good	Good	Good
George Pair Education Center Main	60,661	64	Fair	Fair	Fair	Fair	Fair
George Pair Education- Mobile	1,250	4	Fair	Fair	Good	Fair	Good
Lex2/ Lex4 Adult Education	8,640	55	Fair	Fair	Fair	Fair	Fair

Name of School or Building	Approximate square footage	Approximate age, years	Roof	Exterior Walls	Exterior Windows	Exterior Accessibility	Exterior Doors
Northside Middle School	91,854	19	Fair	Fair	Good	Good	Good
Pine Ridge Middle School	82,669	46	Good	Fair	Good	Good	Fair
Pineview Elementary School Main	55,600	49	Poor	Poor	Good	Good	Poor
Pineview Elementary- Mobiles 1,2,3,4, and 5	3,600	10	Poor	Fair	Fair	Good	Good
R H Fulmer Middle School	107,223	53	Poor	Poor	Poor	Poor	Poor
R H Fulmer Middle School Gym	20,000	18	Poor	Fair	Good	Good	Good
Saluda River Academy Main	53,523	63	Fair	Fair	Good	Good	Good
Saluda River Academy- Mobile 2	720	12	Not Operational	Good	Good	Good	Good
Saluda River Academy- Mobiles 1 and 3	1,440	12	Poor	Fair	Good	Good	Good

Name of School or Building	Approximate square footage	Approximate age, years	Roof	Exterior Walls	Exterior Windows	Exterior Accessibility	Exterior Doors
Springdale Elementary School Main	47,938	51	Poor	Good	Fair	Fair	Fair
Springdale Elementary School Mobiles 1,2,3, and 4	2,900	12	Fair	Fair	Good	Good	Fair
Wood ES	74,407	43	Good	Fair	Good	Good	Good

Name of School or Building	Building Security	Toilet Room Accessibility	Other Interior Assessibility	Administration Area Condition	Common Area and Corridor Condition	Classroom Condition	Gymnasium Condition
Claude Taylpr ES- Mobile	Fair	N/A	N/A	N/A	N/A	Not Operational	N/A
Congaree Elementary School	Fair	Fair	Fair	Fair	Fair	Poor	Fair
Congaree/ Wood Early Childhood	Fair	Good	Good	Fair	Good	Fair	N/A
Cyril B. Busbee Creative Arts Academy	Fair	Good	Good	Fair	Good	Good	Good
Davis Early Childhood Center Main	Fair	Fair	Fair	Fair	Fair	Fair	Fair
Davis Early Childhood Center Mobiles 1,2,3, and 4	Fair	Good	Good	N/A	N/A	Good	N/A
George Pair Education Center Main	Fair	Fair	Fair	Fair	Fair	Poor	Fair
George Pair Education- Mobile	Fair	Good	Good	N/A	N/A	Good	N/A
Lex2/ Lex4 Adult Education	Fair	Fair	Fair	Poor	Fair	Poor	Fair

Name of School or Building	Building Security	Toilet Room Accessibility	Other Interior Assessibility	Administration Area Condition	Common Area and Corridor Condition	Classroom Condition	Gymnasium Condition
Northside Middle School	Fair	Very Good	Good	Good	Very Good	Good	Good
Pine Ridge Middle School	Fair	Good	Good	Good	Good	Good	Good
Pineview Elementary School Main	Fair	Good	Good	Fair	Good	Fair	Good
Pineview Elementary- Mobiles 1,2,3,4, and 5	Fair	Good	Good	N/A	N/A	Fair	N/A
R H Fulmer Middle School	Fair	Fair	Fair	Fair	Fair	Fair	Good
R H Fulmer Middle School Gym	Poor	Good	Good	Good	Good	N/A	Good
Saluda River Academy Main	Fair	Fair	Poor	Poor	Poor	Poor	Fair
Saluda River Academy- Mobile 2	Fair	Fair	Fair	N/A	N/A	Poor	N/A
Saluda River Academy- Mobiles 1 and 3	Fair	Fair	Fair	N/A	N/A	Fair	N/A

Name of School or Building	Building Security	Toilet Room Accessibility	Other Interior Assessability	Administration Area Condition	Common Area and Corridor Condition	Classroom Condition	Gymnasium Condition
Springdale Elementary School Main	Fair	Fair	Fair	Fair	Fair	Fair	Good
Springdale Elementary School Mobiles 1,2,3, and 4	Fair	Fair	Fair	N/A	N/A	Fair	N/A
Wood ES	Fair	Good	Good	Fair	Good	Fair	Good

Name of School or Building	Auditorium/ Multipurpose Area Condition	Kitchen Condition	Toilet Room Condition	Administration HVAC	Classroom HVAC	Other HVAC	Main Electrical Entrance
Airport High School Main	Good	Good	Good	Good	Good	Good	Good
Airport High School- Gym Complex	N/A	Good	Very Good	Good	Good	Good	Good
Airport High School Vocational	N/A	N/A	Fair	Poor	Poor	Poor	Fair
Brookland-Cayce Grammer ES	N/A	Poor	Fair	Poor	Poor	Poor	Fair
Brooklyn-Cayce- Grammer Relocatables 1-4	N/A	N/A	Fair	N/A	Fair	N/A	Good
Brooklyn-Cayce High School- Main Building	Poor	N/A	Poor	Poor	Poor	Poor	Poor
Brookland-Cayce High School - Vocational Bldg	N/A	N/A	Fair	Poor	Poor	Poor	Poor
Brookland-Cayce High School Gym	N/A	N/A	Poor	Poor	Poor	Poor	Poor
Claude Taylor ES	N/A	Poor	Poor	Poor	Poor	Poor	Fair

Name of School or Building	Auditorium/ Multipurpose Area Condition	Kitchen Condition	Toilet Room Condition	Administration HVAC	Classroom HVAC	Other HVAC	Main Electrical Entrance
Claude Taylpr ES- Mobile	N/A	N/A	N/A	N/A	Poor	N/A	Poor
Congaree Elementary School	N/A	Fair	Fair	Poor	Poor	Poor	Fair
Congaree/ Wood Early Childhood	N/A	N/A	Good	Fair	Fair	Fair	Good
Cyril B. Busbee Creative Arts Academy	N/A	Good	Good	Good	Good	Good	Good
Davis Early Childhood Center Main	N/A	Poor	Poor	Poor	Poor	Poor	Fair
Davis Early Childhood Center Mobiles 1,2,3, and 4	N/A	N/A	Fair	N/A	Fair	N/A	Good
George Pair Education Center Main	N/A	Poor	Poor	Poor	Poor	Poor	Fair
George Pair Education- Mobile	N/A	N/A	Good	N/A	Good	N/A	Good
Lex2/ Lex4 Adult Education	N/A	Poor	Poor	Poor	Poor	Poor	Fair

Name of School or Building	Auditorium/ Multipurpose Area Condition	Kitchen Condition	Toilet Room Condition	Administration HVAC	Classroom HVAC	Other HVAC	Main Electrical Entrance
Northside Middle School	N/A	Good	Good	Fair	Fair	Fair	Good
Pine Ridge Middle School	N/A	Poor	Fair	Fair	Fair	Fair	Good
Pineview Elementary School Main	N/A	Poor	Fair	Fair	Fair	Fair	Fair
Pineview Elementary- Mobiles 1,2,3,4, and 5	N/A	N/A	Good	N/A	Good	N/A	Good
R H Fulmer Middle School	N/A	Poor	Fair	Poor	Poor	Poor	Fair
R H Fulmer Middle School Gym	N/A	N/A	Good	Fair	Fair	Fair	Good
Saluda River Academy Main	N/A	Poor	Fair	Poor	Poor	Poor	Poor
Saluda River Academy- Mobile 2	N/A	N/A	Fair	N/A	Fair	N/A	Good
Saluda River Academy- Mobiles 1 and 3	N/A	N/A	Fair	N/A	Fair	N/A	Good

Name of School or Building	Auditorium/ Multipurpose Area Condition	Kitchen Condition	Toilet Room Condition	Administration HVAC	Classroom HVAC	Other HVAC	Main Electrical Entrance
Springdale Elementary School Main	N/A	Poor	Fair	Poor	Poor	Poor	Fair
Springdale Elementary School Mobiles 1,2,3, and 4	N/A	N/A	Fair	N/A	Fair	N/A	Fair
Wood ES	N/A	Poor	Fair	Poor	Poor	Poor	Fair

Name of School or Building	Electrical Distribution	Lighting	Plumbing	Fire Alarm	Fire Sprinkler
Airport High School Main	Good	Good	Good	Very Good	Good
Airport High School- Gym Complex	Good	Good	Good	Very Good	Very Good
Airport High School Vocational	Fair	Fair	Fair	Good	N/A
Brookland-Cayce Grammer ES	Fair	Good	Poor	Good	N/A
Brooklyn-Cayce- Grammer Relocatables 1-4	Good	Fair	Good	Good	N/A
Brooklyn-Cayce High School- Main Building	Poor	Fair	Poor	Fair	N/A
Brookland-Cayce High School - Vocational Bldg	Poor	Fair	Poor	Fair	N/A
Brookland-Cayce High School Gym	Poor	Fair	Poor	Fair	N/A
Claude Taylor ES	Fair	Good	Poor	Good	N/A

Name of School or Building	Electrical Distribution	Lighting	Plumbing	Fire Alarm	Fire Sprinkler
Claude Taylpr ES- Mobile	Poor	Poor	Poor	N/A	N/A
Congaree Elementary School	Fair	Good	Fair	Good	N/A
Congaree/ Wood Early Childhood	Good	Good	Good	Good	Good
Cyril B. Busbee Creative Arts Academy	Good	Good	Good	Very Good	Very Good
Davis Early Childhood Center Main	Fair	Good	Poor	Good	N/A
Davis Early Childhood Center Mobiles 1,2,3, and 4	Good	Fair	Good	Good	N/A
George Pair Education Center Main	Fair	Fair	Poor	Good	N/A
George Pair Education- Mobile	Good	Good	Good	Good	N/A
Lex2/ Lex4 Adult Education	Fair	Fair	Poor	Good	N/A

Name of School or Building	Electrical Distribution	Lighting	Plumbing	Fire Alarm	Fire Sprinkler
Northside Middle School	Good	Good	Good	Very Good	N/A
Pine Ridge Middle School	Good	Good	Fair	Good	Good
Pineview Elementary School Main	Fair	Good	Poor	Good	N/A
Pineview Elementary- Mobiles 1,2,3,4, and 5	Good	Fair	Fair	Good	N/A
R H Fulmer Middle School	Fair	Good	Poor	Very Good	N/A
R H Fulmer Middle School Gym	Good	Good	Fair	Good	N/A
Saluda River Academy Main	Fair	Fair	Poor	Good	N/A
Saluda River Academy- Mobile 2	Good	Fair	Good	Good	N/A
Saluda River Academy- Mobiles 1 and 3	Good	Fair	Good	Good	N/A

Name of School or Building	Electrical Distribution	Lighting	Plumbing	Fire Alarm	Fire Sprinkler
Springdale Elementary School Main	Fair	Good	Poor	Good	N/A
Springdale Elementary School Mobiles 1,2,3, and 4	Fair	Fair	Fair	Good	N/A
Wood ES	Fair	Fair	Fair	Good	N/A

Name of School or Building	Comments on building exterior
Airport High School Main	Sealants are aged and failing. Staining and cracking on walls. Window panes are fogged. Trim needs paint. Lack of expansion joint has damaged brick. Windows are rotting. Roof drains are missing domes. No counter flashing at roof vents. Blisters in roofing membrane. Roof has vegetation growth, ponding water, and clogged downspouts.
Airport High School- Gym Complex	Walls have staining. Sealants need repair. Brick needs some repointing. Roof access ladder is not secured. Roof have granule loss. Sealant at counter flashing has been installed improperly. Roof base flashing is sagging.
Airport High School Vocational	Roof canopys need paint. Bad sealants and spalling brick. Trim/ door needs painting. Roof has sagging base flashing.
Brookland-Cayce Grammer ES	Sealants poor. finish wearing off windows.
Brooklyn-Cayce- Grammer Relocatables 1-4	- Mobile classrooms (4) in use.
Brooklyn-Cayce High School- Main Building	Fine Arts section was added in 2012 and is in good condition.
Brookland-Cayce High School - Vocational Bldg	I2 Complex addition was built in 2012 and is in good condition.
Brookland-Cayce High School Gym	
Claude Taylor ES	Entries need painting. Soffit deterioration. Window infill panels have failed seals. Roof sheet metal has rusted fasteners. Roof vents are missing counter flashing. Expansion joint repairs have failed. Vegetation growth on roof. Base flashing is sagging.

Name of School or Building	Comments on building exterior
Claude Taylpr ES- Mobile	Whole building in severe deterioration. Steps are unsafe. Missing windows.
Congaree Elementary School	Sealants are bad. Doors need paint. Window finish failing. Stucco at entry failing. Roof soffits are failing. Some doors are sagging at the hinges. Trim needs paint. Tectum damaged at soffits roof edge. Some windows rusting. Roof membrane is splitting. Gutters are holding water. Vegetation growth on roof. No counter flashing at roof vents. Metal coping is not terminated. Base flashing slippage. 2007 plumbing, electrical upgrades & roof repairs.
Congaree/ Wood Early Childhood	Roof has granule loss. Paint is flaking on coping. Roof has vegetation growth. Low base flashing height. Fascia needs paint/ coating. Doors need paint. Window seals deteriorating. Missing sealants.
Cyril B. Busbee Creative Arts Academy	Sealant failing. some brick cladding cracks, spalling, cracking at lintels. Some windows fogged and sill flashings leaking. Roof has granule loss. Roof coping is not terminated at wall. Roof base flashing not adhered. Weep holes have been caulked.
Davis Early Childhood Center Main	Sealants are aging, failing in some places. Roof vegetation growth. Rusting fasteners on Roof. Granule loss on Roof. No counter flashings at roof vents. Roof coping is not terminated. Blisters in the roofing membrane.
Davis Early Childhood Center Mobiles 1,2,3, and 4	Walls need paint. Deteriorated siding and rotten skirt. Roof is sagging in a few areas.
George Pair Education Center Main	Building additions: 1953, 1954, 1962, 1971 Sealant has 2-4 years left. Doors have a lot of corrosion around them. Paint on doors and windows are heavily faded.
George Pair Education- Mobile	Skirt needs repaired and painted. Metal roof is missing flashings.
Lex2/ Lex4 Adult Education	Roofing membrane has some blisters. No counter flashing at roof vents. Granular loss at base flashing on roof.

Name of School or Building	Comments on building exterior
Northside Middle School	Sealants are failing at control joints and around windows. Some efflorescence staining. Sheet metal panels are not fully seamed. Roof base flashings is not adhered in some areas.
Pine Ridge Middle School	Corridors, classrooms updated 2012. Current new construction for new cafeteria and kitchen. Efflorescence at front entry and needs paint. Doors need paint and sealant. EIFS is cracking in some areas. Fascia needs paint. Damaged louvers at rear of school. Missing counter flashing on roof vents. Some debris on roof.
Pineview Elementary School Main	Gy and music-art wing is an addition approximately 2000. Classroom wing addition are approximately 1970 and 1980. Sealants are in poor condition. Fascias are deteriorated and tectum is exposed. Efflorescence and spalling on brick. Roof edges have several leaks. Soffits are in poor condition. Roof coping fasteners are too short and beginning to back out. Roof access ladder is rusting. Roof drains are clogged. Several areas of ponding water. Roof area has vegetation growth. EPDM laps and patches are failing. Several splits in membrane.
Pineview Elementary- Mobiles 1,2,3,4, and 5	Mobile classrooms (5) in use. Siding needs painting. Skirt is rotten. One window frame is rotten.
R H Fulmer Middle School	Gym and classrooms wing addition was approximately in 1999. Front entry soffits are damaged/ tectum roof soffits are damaged. Sealants are in poor condition. Areas of eroded concrete. Displace gravel felt scrim exposed. Roof edge is collapsing. Roof has vegetation growth. Missing counter flashing on roof vents. Roof base flashing has a rip in it. Roof to wall termination open.
R H Fulmer Middle School Gym	Sealants are failing. Roof has gravel displacement- exposed felt scrim. Roof base flashing is crazing. Roof has vegetation growth. Expansion joint is beyond service life cycle. Counter flashing is backing out.
Saluda River Academy Main	Gym, music-art, classroom wing addition is approximately built in 1971. Sealants are at 90% of life. Minor cracking in brickwork. Roof vertical seam lap coating is failing. Roof drains are clogged. Fascia metal and gutter have flaking paint. Roof expansion joint if failing. Roof has blisters and several areas of ponding water.
Saluda River Academy- Mobile 2	Roof has collapsed. Mobile classroom is not operational.
Saluda River Academy- Mobiles 1 and 3	Siding is coming loose, needs paint. Skirts are rotten. Shingles are beyond repair.

Name of School or Building	Comments on building exterior
Springdale Elementary School Main	Gym, music-art, classroom wing addition is approximately 2000. Sealants are old. Staining on walls. Some windows and doors are old. Roof edge has standing water. Roof has vegetation growth. No counter flashing at roof vents. Some coping is rusting. Exposed fasteners at base flashing. Improper termination of coping.
Springdale Elementary School Mobiles 1,2,3, and 4	Skirt is damaged. Fascia needs painting. Soffits have some damage. Shingles have some granule loss.
Wood ES	EIFS areas need refinished. No sealant at fenestration. Entry soffits are falling in. Doors and fascia need paint. Roof has some areas of ponding water.

Name of School or Building	Comments on building accessibility
Airport High School Main	
Airport High School- Gym Complex	
Airport High School Vocational	
Brookland-Cayce Grammer ES	
Brooklyn-Cayce- Grammer Relocatables 1-4	
Brooklyn-Cayce High School- Main Building	- Several staff restrooms do not meet accessibility standards
Brookland-Cayce High School - Vocational Bldg	I2 Complex addition was built in 2012 and is in good condition.
Brookland-Cayce High School Gym	
Claude Taylor ES	

Name of School or Building	Comments on building accessibility
Claude Taylpr ES- Mobile	
Congaree Elementary School	
Congaree/ Wood Early Childhood	
Cyril B. Busbee Creative Arts Academy	
Davis Early Childhood Center Main	Gym and Cafeteria are additions approximately built in 2005.
Davis Early Childhood Center Mobiles 1,2,3, and 4	Mobile classrooms (3) in use approx 12 years old. Mobile classrooms (1) in use approx 4 years old.
George Pair Education Center Main	
George Pair Education- Mobile	
Lex2/ Lex4 Adult Education	

Name of School or Building	Comments on building accessibility
Northside Middle School	
Pine Ridge Middle School	
Pineview Elementary School Main	Stage located in cafeteria area has no ADA access.
Pineview Elementary- Mobiles 1,2,3,4, and 5	
R H Fulmer Middle School	
R H Fulmer Middle School Gym	
Saluda River Academy Main	
Saluda River Academy- Mobile 2	
Saluda River Academy- Mobiles 1 and 3	

Name of School or Building	Comments on building accessibility
Springdale Elementary School Main	
Springdale Elementary School Mobiles 1,2,3, and 4	
Wood ES	Stage located in cafeteria has no ADA access.

Name of School or Building	Comments on building interior finishes
Airport High School Main	Upgrade flooring. Main office and lobby areas renovated in 2004.
Airport High School- Gym Complex	
Airport High School Vocational	
Brookland-Cayce Grammer ES	- Gym, music-art, classroom wing addition +/- 1971 - Stage located in cafeteria area (No ADA access)
Brooklyn-Cayce- Grammer Relocatables 1-4	
Brooklyn-Cayce High School- Main Building	Fine Arts section was added in 2012 and is in good condition.
Brookland-Cayce High School - Vocational Bldg	I2 Complex addition was built in 2012 and is in good condition.
Brookland-Cayce High School Gym	- Upgrade flooring - carpet
Claude Taylor ES	Stage located in cafeteria area (No ADA access)

Name of School or Building	Comments on building interior finishes
Claude Taylpr ES- Mobile	Mobile used for storage only.
Congaree Elementary School	
Congaree/ Wood Early Childhood	
Cyril B. Busbee Creative Arts Academy	
Davis Early Childhood Center Main	
Davis Early Childhood Center Mobiles 1,2,3, and 4	
George Pair Education Center Main	
George Pair Education- Mobile	
Lex2/ Lex4 Adult Education	

Name of School or Building	Comments on building interior finishes
Northside Middle School	
Pine Ridge Middle School	
Pineview Elementary School Main	Corridor floors replaced approximately 2000.
Pineview Elementary- Mobiles 1,2,3,4, and 5	
R H Fulmer Middle School	Stage located in cafeteria area has no ADA access.
R H Fulmer Middle School Gym	Roof leaks, paint peeling- repaint rooms
Saluda River Academy Main	Stage located in cafeteria area has no ADA access.
Saluda River Academy- Mobile 2	
Saluda River Academy- Mobiles 1 and 3	

Name of School or Building	Comments on building interior finishes
Springdale Elementary School Main	Stage located in cafeteria area has no ADA access.
Springdale Elementary School Mobiles 1,2,3, and 4	Secure ceiling tile in grid, trip hazard where mobile halves come together.
Wood ES	

Name of School or Building	Comments on MEP
Airport High School Main	
Airport High School- Gym Complex	
Airport High School Vocational	
Brookland-Cayce Grammer ES	- Lighting has been updated to T8
Brooklyn-Cayce- Grammer Relocatables 1-4	
Brooklyn-Cayce High School- Main Building	Fine Arts section was added in 2012 and is in good condition.
Brookland-Cayce High School - Vocational Bldg	I2 Complex addition was built in 2012 and is in good condition.
Brookland-Cayce High School Gym	- Current lighting T8
Claude Taylor ES	Lighting has been updated to T8.

Name of School or Building	Comments on MEP
Claude Taylpr ES- Mobile	
Congaree Elementary School	Lighting has been updated to T8.
Congaree/ Wood Early Childhood	
Cyril B. Busbee Creative Arts Academy	
Davis Early Childhood Center Main	
Davis Early Childhood Center Mobiles 1,2,3, and 4	
George Pair Education Center Main	Lighting has been updated to T8.
George Pair Education- Mobile	
Lex2/ Lex4 Adult Education	

Name of School or Building	Comments on MEP
Northside Middle School	
Pine Ridge Middle School	Lighting has been updated to T8.
Pineview Elementary School Main	Lighting has been updated to T8.
Pineview Elementary- Mobiles 1,2,3,4, and 5	
R H Fulmer Middle School	Lighting has been updated to T8.
R H Fulmer Middle School Gym	Lighting has been updated to T8
Saluda River Academy Main	Lighting has been updated to T8.
Saluda River Academy- Mobile 2	
Saluda River Academy- Mobiles 1 and 3	

Name of School or Building	Comments on MEP
Springdale Elementary School Main	Lighting has been updated to T8.
Springdale Elementary School Mobiles 1,2,3, and 4	
Wood ES	Lighting has been upgraded to T8.

Name of School or Building	Comments on building life safety and security
Airport High School Main	Upgrade security camera, locks, signage.
Airport High School- Gym Complex	Upgrade security cameras.
Airport High School Vocational	Upgrade security cameras, locks, signage.
Brookland-Cayce Grammer ES	
Brooklyn-Cayce- Grammer Relocatables 1-4	- Safety, security cameras
Brooklyn-Cayce High School- Main Building	- Safety: upgrade security cameras, locks, Signage
Brookland-Cayce High School - Vocational Bldg	I2 Tech Complex addition was built in 2012 and is in good condition. - Safety: upgrade security cameras, locks, signage
Brookland-Cayce High School Gym	- Current lighting T8
Claude Taylor ES	

Name of School or Building	Comments on building life safety and security
Claude Taylpr ES- Mobile	
Congaree Elementary School	
Congaree/ Wood Early Childhood	
Cyril B. Busbee Creative Arts Academy	
Davis Early Childhood Center Main	School has security cameras.
Davis Early Childhood Center Mobiles 1,2,3, and 4	Buildings have security cameras.
George Pair Education Center Main	Stage located in cafeteria area has no ADA access. Building has security cameras.
George Pair Education- Mobile	Building has security cameras.
Lex2/ Lex4 Adult Education	

Name of School or Building	Comments on building life safety and security
Northside Middle School	
Pine Ridge Middle School	
Pineview Elementary School Main	Building has security cameras.
Pineview Elementary- Mobiles 1,2,3,4, and 5	Buildings have security cameras.
R H Fulmer Middle School	
R H Fulmer Middle School Gym	Upgrade security cameras, locks- hardware
Saluda River Academy Main	Additional security cameras needed.
Saluda River Academy- Mobile 2	
Saluda River Academy- Mobiles 1 and 3	Building has security cameras.

Name of School or Building	Comments on building life safety and security
Springdale Elementary School Main	
Springdale Elementary School Mobiles 1,2,3, and 4	
Wood ES	

Name of School or Building	
Airport High School Main	
Airport High School- Gym Complex	
Airport High School Vocational	
Brookland-Cayce Grammer ES	
Brooklyn-Cayce- Grammer Relocatables 1-4	
Brooklyn-Cayce High School- Main Building	
Brookland-Cayce High School - Vocational Bldg	
Brookland-Cayce High School Gym	
Claude Taylor ES	

Name of School or Building	
Claude Taylpr ES- Mobile	
Congaree Elementary School	
Congaree/ Wood Early Childhood	
Cyril B. Busbee Creative Arts Academy	
Davis Early Childhood Center Main	
Davis Early Childhood Center Mobiles 1,2,3, and 4	
George Pair Education Center Main	
George Pair Education- Mobile	
Lex2/ Lex4 Adult Education	

Name of School or Building	
Northside Middle School	
Pine Ridge Middle School	
Pineview Elementary School Main	
Pineview Elementary- Mobiles 1,2,3,4, and 5	
R H Fulmer Middle School	
R H Fulmer Middle School Gym	
Saluda River Academy Main	
Saluda River Academy- Mobile 2	
Saluda River Academy- Mobiles 1 and 3	

Name of School or Building	
Springdale Elementary School Main	
Springdale Elementary School Mobiles 1,2,3, and 4	
Wood ES	